

Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 1 –

Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 2 – Oily soil on pit bank, oil on surface of pit



Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 3 – Oily soil on pit bank, oil on surface of pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 4 – Oily soil on pit bank, oil on surface of pit in southwest corner

Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 5 – View north at pit with oil on the surface, oil on pit berms in northeast corner



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating – Kloefkorn Battery – Rem #10741, Spill ID 453191
Inspection Date: 02/18/2020



Photo # 6 – Oily soil and tumbleweeds on southwest corner of pit berm

