

Banta Ridge 5-17-1-103

API: 05-103-10076

Inspection: 700400139



39.95924, -108.9863, 5764.6ft, 308°
02/21/2020 11:20:12 AM

Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge 5-17-1-103

API: 05-103-10076

Inspection: 700400139



Photo 2. Well head.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge 5-17-1-103

API: 05-103-10076

Inspection: 700400139



Photo 3. Separator & meter building.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Banta Ridge 5-17-1-103

API: 05-103-10076

Inspection: 700400139



Photo 4. Tank.



Banta Ridge 5-17-1-103

API: 05-103-10076

Inspection: 700400139



Photo 5. Battery sign.

