

Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #1 looking south



Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #2 Looking south west

Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #3 looking west



Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #4 looking northeast. Flags show sample locations. South of where photo was taken, soil has been shown to be below table 910-1 standards.

Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #5 looking west, north west. Flags show area where samples were collected.



Inspection Photos
location 116704
Remediation Projects 11554
Inspection Date: 7/30/2019
Photos taken by Kris Neidel



Photo #6 east side of pit. Truck is parked on access road to pit facility.

