

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2019

Submitted Date:

02/24/2020

Document Number:

694500173**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
NEIDEL, KRIS 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95520Name of Operator: WESCO OPERATING INCAddress: 120 S DURBIN STREETCity: CASPER State: WY Zip: 82602**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
116704	PIT	AC			-	GOVERNMENT TRELEAVEN TB	EI
439286	SPILL OR RELEASE	AC	10/10/2014		-	SPILL/RELEASE POINT	EI

General Comment:

On 7/30/2019, COGCC Staff, Kris Neidel was present to observe pit sampling. Weather was overcast and 70 degrees. Pit Facility ID #116704 is a part of Remediation Project #11554. At the time of inspection, Wesco Staff, Dave Weinert was collecting confirmation soil samples of pit bottom. Previous soil samples (7/16/18) indicated soil concentrations on; the south end of the pit to be below 910-1 standards, the north side of the pit required further excavation. In summer of 2019 Wesco had excavated the North side of the pit bottom and pit walls biased on visual and olfactory observations. A total of 7 soil samples were collected. The specific sample locations were selected by digging with a spade and pick axe around the predetermined sample area(s) and selecting the sample locations that appear to contain the highest impact. Wesco Staff collected and packaged samples for hand delivery to the Lab. NO water was observed in the pit. By 3/24/2020, Wesco should submit a Form 19 for spill 439286, if information is adequate to close please do so, if spill requires further remediation, a Form 27 should be submitted. See Photos Attached

Inspected FacilitiesFacility ID: 116704 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 439286 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500174	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075460