

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 02/18/2020



Photo # 1 –

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 02/18/2020



Photo # 2 – Former tank battery area. Tanks and stairs have been removed since previous inspection

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 02/18/2020



Photo # 3 – Former tank battery area. Vertical separator foundation and fencing materials remain



Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 02/18/2020



02.18.2020

Photo # 4 – Former pit requiring investigation, remediation and reclamation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Markus Production Inc. – Rem #13154 – Pits 107649, 119049
Inspection Date: 02/18/2020



Photo # 5 – Former pit requiring investigation, remediation and reclamation