

**Inspection Photos**  
**Location Name: State Pronghorn X-29 PAD**  
**Location ID: 438608**



**Photo 1 – Wellheads**




**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: State Pronghorn X-29 PAD**  
**Location ID: 438608**



**Photo 3 – Separators**



**Photo 4 – Stained Soil at X-D-29 Wellhead**

**Inspection Photos**  
**Location Name: State Pronghorn X-29 PAD**  
**Location ID: 438608**



**Photo 5 – Wellhead Sign missing at 43-13-29 Well**

