

Inspection Photos
Location Name: Remora LC34-745 PAD
Location ID: 439896



Photo 1 – Haley LC27-711 & 715 Wellheads



Photo 2 – Haley LC27-715 missing Wellhead Sign

Inspection Photos
Location Name: Remora LC34-745 PAD
Location ID: 439896



Photo 3 – Unused Chemical Tank at Haley LC27-711 & 715 Wellheads



Photo 4 – Remora LC34-715 & 725 Wellheads

Inspection Photos
Location Name: Remora LC34-745 PAD
Location ID: 439896



Photo 5 – Remora LC34-745 & 735 Wellheads

Photo 6 – Haley LC27-735 & 745 Wellheads