

Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /150 Pad

Location ID: 334554



Photo #0640 from entrance to location



Photo #0641 Unused 2" pipe on separator.