



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Luis Guerrero (l.guerrero@kosinm.com)
Submission Date: Feb 13, 2020 8:20:39 PM MST
Server Receive Date: Feb 13, 2020 8:20:46 PM MST
Reference Number: 20200214-18132997341
Location: 16A Road 51921, Bloomfield, NM 87413, USA
Feb 13, 2020 8:07:24 PM MST [[View Map](#)]

Information

Name	l.guerrero@kosinm.com
Date	Aug 8, 2019
Well Name	KAIME FEDERAL GAS UNIT 2
API Number	50670906000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Removed unused piping and insulation.

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed



Cleaned up stained soils.

Completed work description of corrective action 3
Photo of fourth corrective action completed



Installed drip catch box on muffler.

Completed work description of corrective action 4
Additional photos



Cleaned up stained soils around the wellhead.

Summary of all work completed

Removed unused piping. Cleaned up stained soils around the wellhead and muffler. Installed drip box on muffler. Picked up all trash and debris.