



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 13, 2020 9:20:09 PM MST
Server Receive Date:	Feb 13, 2020 9:20:14 PM MST
Reference Number:	20200214-18132998466
Location:	16A Road 51921, Bloomfield, NM 87413, USA Feb 13, 2020 9:17:11 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Jun 17, 2019
Well Name	WILBOURN FEDERAL GAS UNIT 1
API Number	50670723300
Select State	Colorado
Action Complete	Compliance Inspection Actions Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Removed trash and debris from location.

Photo of second corrective action completed



Completed work description of corrective action 2

.

Completed work description of corrective action 3

.

Completed work description of corrective action 4
Summary of all work completed

.
Removed trash and debris from well site project area.