



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 14, 2020 1:49:54 PM MST
Server Receive Date:	Feb 14, 2020 1:50:01 PM MST
Reference Number:	20200214-18133074377
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Feb 14, 2020 1:49:48 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Jul 22, 2019
Well Name	UTE GAS UNIT 01A-20 2
API Number	50670678000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Contaminated Soils Replaced/Repaired Well Sign

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soils around muffler and installed drip box.

Photo of second corrective action completed



Completed work description of corrective action 2
Completed work description of corrective action 3
Completed work description of corrective action 4
Summary of all work completed

Replaced well site sign.

.

.

Cleaned up stained soils around the muffler. Installed drip box on muffler exhaust. Replaced well site sign.