

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Feb 14, 2020 12:12:15 PM MST
Server Receive Date:	Feb 14, 2020 12:14:54 PM MST
Reference Number:	20200214-18133059724
Location:	1330 Airport Rd, Durango, CO 81303, USA Feb 14, 2020 12:14:37 PM MST [View Map]

Name	colen@horizonenvservices.com
Date	Feb 14, 2020
Location Name (Other)	southern ute dd2
Location API (Other)	0506709694
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Replaced/Repaired Well Sign



installed sign
same
same
same
installed sign
installed sign