

## Inspection Photos

Location Name: KIEKO 14-6 FOLLOWUP CA DATE IMMEDIATELY

API#: 05-071-08150

INSP. #: 695102209



**PHOTO 1: LOCATION**



**PHOTO 2: WELL SIGN**



**Inspection Photos**  
**Location Name: KIEKO 14-6 FOLLOWUP CA DATE IMMEDIATELY**  
**API#: 05-071-08150**  
**INSP. #: 695102209**

**Calibration Report**

Report Date: 3/20/19 1:50 PM Collection Time: 3/20/19 12:54 PM

Device ID: 102108629 System: Contact # 719-846-7898  
 Location: Keiko 14-6 Field: Raton Basin  
 State: Colorado  
 Producer: Evergreen Natural Resources  
 Purchaser: Colorado Interstate Gas

**Section 2 - Setup**

Current Plate Size: 0.625 Tap Type: Flange  
 Pipe Size: 2.061 SP Tap Location: Up Stream  
 Atmos. Pressure: 11.4 Temperature Bias: 0  
 Pressure Base: 14.73 Temperature Base: 60

State Inspected? Yes No Dirty Yes No Nicked? Yes No  
 Edges Sharp? Yes No Plate Mic'd Yes No Warped? Yes No  
 Seal Ring Damaged? Yes No Pitted Yes No Borel Downstream Yes No

**Section 3 - Liquid and Gas Inspection**

Tube Inspected? Yes No Nicked? Yes No  
 Dirty? Yes No

**Section 4 - Differential**

DIFFERENTIAL		LEFT		RIGHT		DIFF.		TYP.		FOUND	
PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE
0.00	0.00	0.00	0.00	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
100.00	99.83	100.00	99.83	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
200.00	199.66	200.00	199.66	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
300.00	299.49	300.00	299.49	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
400.00	399.32	400.00	399.32	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
500.00	499.15	500.00	499.15	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
600.00	598.98	600.00	598.98	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
700.00	698.81	700.00	698.81	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
800.00	798.64	800.00	798.64	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
900.00	898.47	900.00	898.47	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
1000.00	998.30	1000.00	998.30	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31

REMARKS: Colorado Oil & Gas Conservation Commission  
 37.19409, -104.82546, 2188.0m, 75°  
 2020/02/25 11:03:43

**Calibration Report**

Report Date: 3/20/19 2:03 PM Collection Time: 3/20/19 1:14 PM

Device ID: 102108629 System: Contact # 719-846-7898  
 Location: Keiko 14-6 Field: Raton Basin  
 State: Colorado  
 Producer: Evergreen Natural Resources  
 Purchaser: Colorado Interstate Gas

**Section 2 - Setup**

Current Plate Size: 0.625 Tap Type: Flange  
 Pipe Size: 2.061 SP Tap Location: Up Stream  
 Atmos. Pressure: 11.4 Temperature Bias: 0  
 Pressure Base: 14.73 Temperature Base: 60

State Inspected? Yes No Dirty Yes No Nicked? Yes No  
 Edges Sharp? Yes No Plate Mic'd Yes No Warped? Yes No  
 Seal Ring Damaged? Yes No Pitted Yes No Borel Downstream Yes No

**Section 3 - Liquid and Gas Inspection**

Tube Inspected? Yes No Nicked? Yes No  
 Dirty? Yes No

**Section 4 - Differential**

DIFFERENTIAL		LEFT		RIGHT		DIFF.		TYP.		FOUND	
PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE	PLATE	NOISE
0.00	0.00	0.00	0.00	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
100.00	99.83	100.00	99.83	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
200.00	199.66	200.00	199.66	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
300.00	299.49	300.00	299.49	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
400.00	399.32	400.00	399.32	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
500.00	499.15	500.00	499.15	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
600.00	598.98	600.00	598.98	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
700.00	698.81	700.00	698.81	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
800.00	798.64	800.00	798.64	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
900.00	898.47	900.00	898.47	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31
1000.00	998.30	1000.00	998.30	11.40	11.31	11.40	11.31	11.40	11.31	11.40	11.31

REMARKS: Colorado Oil & Gas Conservation Commission  
 37.19409, -104.82546, 2186.0m, 88°  
 2020/02/25 11:03:53

**PHOTO 3: GAS METER CAL. LOG**

**PHOTO 4: GAS METER CAL. LOG**

## Inspection Photos

Location Name: KIEKO 14-6 FOLLOWUP CA DATE IMMEDIATELY

API#: 05-071-08150

INSP. #: 695102209



**PHOTO 5: NO NFPA SIGNS POSTED ON PRODUCED  
WATER TANK. Install sign to comply with Rule 210.d.  
CA DATE IMMEDIATELY**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources