

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /3B Pad

Location ID: 334467



Photo #0649 from entrance to location



Photo #0650 Multiple unused bull plugs on top of tank man way covers.

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /3B Pad

Location ID: 334467



Photo #0651 Multiple unused bull plugs on top of tank man way covers.