

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

NORTHWEST A S20-25-11C Surface

Sincerely,
Meghan Jacobs

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

3.0 Attachments..... 9

 3.1 Northwest A S20-25-11C Surface – Job Chart9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Northwest A S20-25-11C** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 30 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404		Ship To #: 3901405		Quote #:		Sales Order #: 0905949638				
Customer: EXTRACTION OIL & GAS -				Customer Rep: HANS						
Well Name: NORTHWEST A			Well #: S20-25-11C			API/UWI #: 05-014-20789-00				
Field: WATTENBERG		City (SAP): BROOMFIELD		County/Parish: BROOMFIELD			State: COLORADO			
Legal Description: NW NW-9-1S-68W-1285FNL-831FWL										
Contractor: ENSIGN DRLG				Rig/Platform Name/Num: ENSIGN 147						
Job BOM: 7521 7521										
Well Type: HORIZONTAL OIL										
Sales Person: HALAMERICA\HX38199				Srv Supervisor: Lance Carpenter						
Job										
Formation Name										
Formation Depth (MD)		Top		Bottom						
Form Type				BHST						
Job depth MD		1610ft		Job Depth TVD		1610				
Water Depth				Wk Ht Above Floor		4				
Perforation Depth (MD)		From		To						
Well Data										
Description	New / Used	Size	ID	Weight	Thread	Grade	Top MD	Bottom MD	Top TVD	Bottom TVD
Casing		9.625		36			0	1610	0	1610
OH		13.5					0	1630	0	1630
Fluid Data										
Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Red Dye Spacer	Red Dye Spacer	10	bbl	8.33					
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
2	SwiftCem	SWIFTCM (TM) SYSTEM	625	sack	13.5	1.74		5	9.17	
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
3	Fresh Water	Fresh Water	122	bbl	8.33					

Cement Left In Pipe	Amount	40	Reason	Shoe Joint
Mix Water:	pH 7	Mix Water Chloride:	100 ppm	Mix Water Temperature:
Cement Temperature:	## °F °C	Plug Displaced by:	8.4 lb/gal Water	Disp. Temperature:
Plug Bumped?	Yes	Bump Pressure:	608 psi	Floats Held?
Cement Returns:	## bbl m3	Returns Density:	## lb/gal kg/m3	Returns Temperature:
Comment JOB WENT WELL. CEMENT VOLUMES WERE SCALED AND VERIFIED. TOP PLUG DROPPED AFTER CEMENT. WASHED UP FIRST 10 BBL ON TOP OF PLUG. SPACER RETURNS AT 70 BBL AWAY. CEMENT TO SURFACE AT 85 BBL AWAY. BUMPED PLUG, FINAL CIRCULATING PRESSURE 608 PSI. TOOK TO 824 PSI. FLOATS HELD WITH .5 BBL BACK. 30 BBL CEMENT TO SURFACE				

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	Comb Pump Rate (bbl/min)	Pump Stg Tot (bbl)	Comments
Event	1	Arrive At Loc	Arrive At Loc	8/31/2019	21:00:00	USER					ARRIVE AT LOCATION. RIG TD AT 21:45 AND STARTED RUNNING CASING.
Event	2	Casing on Bottom	Casing on Bottom	9/1/2019	01:15:00	USER					CASING ON BOTTOM. RIG DOWN CASING CREW. RIG UP HES PLUG CONTAINER AND BEGIN CIRCULATION THROUGH HES SWEDGE.
Event	3	Start Job	Start Job	9/1/2019	01:59:49	COM6	46.00	8.63	0.00	19.80	
Event	4	Safety Meeting	Safety Meeting	9/1/2019	02:00:00	USER	46.00	8.63	0.00	19.80	CREW, RIG CREW AND CUSTOMER REPS HAVE PRE JOB SAFETY MEETING DISCUSSING HAZARDS, RIG OPERATIONS, RED ZONES, MUSTER AREAS, PINCH POINTS, LINE OF FIRE, CONTINGENCIES AND JOB PROCEEDURE
Event	5	Test Lines	Test Lines	9/1/2019	02:04:06	COM6	2819.00	8.47	0.00	23.30	FILL LINES WITH 3 BBL WATER. PRESSURE TEST HES LINES TO 2500 PSI. HELD FOR A FEW MINUTES, TEST GOOD.
Event	6	Pump Spacer 1	Pump Spacer 1	9/1/2019	02:07:39	COM6	62.00	8.31	0.00	23.30	PUMPED 10BBLS OF RED DYE SPACER
Event	7	Pump Cement	Pump Cement	9/1/2019	02:11:42	COM6	126.00	8.30	4.00	11.40	PUMP 193 BBL SWIFTCCEM 13.5# 1.74 YIELD 9.17 GAL 625 SACKS

Event	8	Drop Top Plug	Drop Top Plug	9/1/2019	02:55:40	COM6	33.00	15.10	0.00	219.40	DROPPED TOP PLUG WITH COMPANY MAN ON RIG FLOOR
Event	9	Pump Displacement	Pump Displacement	9/1/2019	02:55:47	COM6	33.00	15.10	0.00	0.00	PUMP 122 BBL DISPLACEMENT WATER (FIRST 10 BBL WASHUP ON TOP OF PLUG
Event	10	Bump Plug	Bump Plug	9/1/2019	03:19:25	COM6	810.00	8.38	0.00	127.40	BUMP PLUG. FINAL CIRCULATING PRESSURE 608 PSI. TOOK TO 824 PSI AND HELD FOR A COUPLE MINUTES. BLED BACK TO CHECK FLOATS, .5 BBL BACK, FLOATS HELD
Event	11	End Job	End Job	9/1/2019	03:29:24	COM6	49.00	8.36	0.00	145.30	
Event	12	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	9/1/2019	03:30:00	USER	54.00	8.31	0.00	145.30	CREW HAS PRE RIG DOWN SAFETY MEETING DISCUSSING SLIPS TRIPS FALLS, PROPER LIFTING, RED ZONES, RIG OPERATIONS, HAZARDS, PROPER PPE AND BEGIN RIGGING DOWN LINES AND EQUIPMENT

3.0 Attachments

3.1 Northwest A S20-25-11C Surface – Job Chart

