

# Inspection Photos

API: 055-06154

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. Vegetation is sparse in areas along the former road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 2.** Facing east along the access road. Vegetation is sparse in areas along the former road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 3.** Facing east toward the location. Vegetation is sparse in areas at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 4.** Facing north toward the location. There area areas where vegetation appears to be establishing well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 5.** Facing north at the Big pit area. There are areas where vegetation does not appear to have established to 80% cover of the reference.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 6.** Facing south at the north side of the Big pit area. Vegetation has not adequately established in areas of the former pit disturbance area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 7.** Facing west at the north side of the location. Vegetation is sparse in areas at the Big pit area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020



## Inspection Photos



**Photo 8.** Facing north toward the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06154 | Date: 2/27/2020