

# Inspection Photos

API: 055-06176

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 1.** Facing north toward access road standing at Lat/Long:37.56491, -104.85848. Vegetation along the road has not established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 2.** Facing north along the access road which does not have adequate vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the location. Vegetation appears to be fully established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 4.** Facing southwest toward the location. Vegetation appears to be fully established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 5.** Facing east toward the access road which entered from the main subdivision road. Standing at Lat/Long:37.56620,-104.85827. Vegetation has not established along this area of the former road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 6.** Facing back to the west along the access road. Vegetation has not established along this area of the road. And the road regraded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 7.** There is noxious weeds along the access road at Lat/Long: 37.56628, - 104.85686.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020

## Inspection Photos



**Photo 8.** Facing east toward the access road near Lat/Long: 37.56628, -104.85686. The remainder of the road to the main subdivision road has vegetation established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06176 | Date: 2/27/2020