

RECEIVED

OCT 17 1978



00500726

JIM SNYDER DRILLING COMPANY  
1507 Denver Club Building  
Denver, Colorado 80202

COLO. OIL & GAS CONS. COMM.

PLUGGING REPORT

Well Name CUNNINGHAM #10-1

Location SE 1/4 - SE 1/4

10-16<sup>3</sup> - 48 W

Operator S. M. Hyber Corp

This well was filled with Wt. 9.4 mud.

15 sacks were put at the bottom of surface pipe and 10  
sacks at the top of the surface pipe.

Bottom hole plugs (if any) 25 SKS @ 3906

20 SKS @ 1209

To my knowledge, no junk was left in the hole.

Signed: Gene Owens  
Toolpusher

JIM SNYDER DRILLING COMPANY

Date 7-23-78

BEST IMAGE  
AVAILABLE

JUL 27 1978

RECEIVED

OCT 17 1978

JIM SNYDER DRILLING COMPANY  
1507 Denver Club Building  
Denver, Colorado 80202

COLO. OIL & GAS CONS. COMM.

PLUGGING REPORT

Well Name Cunningham #10-1

Location SE 1/4 - SE 1/4  
10-16<sup>s</sup> - 48<sup>w</sup>

Operator S. M. Hyber Corp

This well was filled with Wt. 9.4 mud.

15 sacks were put at the bottom of surface pipe and 10  
sacks at the top of the surface pipe.

Bottom hole plugs (if any) 25 SXS @ 3906  
20 SXS @ 1209

To my knowledge, no junk was left in the hole.

Signed: Gene Owens  
Toolpusher

JIM SNYDER DRILLING COMPANY

Date 7-23-78

JUL 27 1978