



WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

Well Name CUNNINGHAM 10-1 API Number 05 - 017 - 6216
Operator HUBER Permit # 78 370
Location SE SE 10 16S 48W County CHEYENNE
Field WC Inspector SHELTON

AL/PA/DA Inspection Results:

Well Status:

Pass ☒ Y Fail(N) ☐ Date 7/16/91 ND ☐ DG ☐ WO ☐ PR ☐ SI ☐ TA ☐

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES ☐ NO ☐ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: _____ Sign: Yes ☐ No ☐
Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes ☐ No ☐
Bradenhead Press: _____ Fluid: No ☐ Yes ☐ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 7/78 Date Permit Expired: _____
Hole Plugged: Yes ☒ No ☐ Pits Backfilled: Yes ☒ No ☐
Material Buried: Yes ☐ No ☐ N/A ☒ Site Clean: Yes ☒ No ☐
Bond Release OK: Yes ☒ No ☐ Fed ☐ Hole Marker: Yes ☐ No ☒

Date of Safety/Status Inspection 7/16/91

Comments: OLD DA / SITE RESTORED IN EX CULT FIELD /
NO SIGN SURF CSG / FOUND CUTTINGS

Violations: Yes ☐ No ☐ Notice Sent: Yes ☐ No ☐ Date Sent: _____