

Inspection Photos

Location Name: LARAMIE ENERGY LLC Sup & Shep /25-11 Pad

Location ID: 334440



Photo #0660 from entrance to location



Photo #0661 unused chokes.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Sup & Shep /25-11 Pad

Location ID: 334440



Photo #0662 unused chokes.




Photo #0663 unused bull plug and thread half.