

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2020

Submitted Date:

02/24/2020

Document Number:

688000364

**FIELD INSPECTION FORM**

Loc ID 399960 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10330  
Name of Operator: INVESTMENT EQUIPMENT LLC  
Address: 412 W PLATTE AVE  
City: FT MORGAN State: CO Zip: 80701

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451925	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

**General Comment:**

Environmental inspection related to apparent spill from SE corner of the eastern produced water pit. Spill ID 451925 remains open and requires a supplemental Form 19 requesting NFA status for closure.

**Inspected Facilities**

Facility ID: 451925 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Location photographs document an apparent produced water spill from the southeast corner area of Pit 117587 (larger, eastern produced water pit) that ran into the low area east of the pit area. There is obvious erosion near the southeast corner of the pit and associated sediment deposition further east of the pit that is not consistent with the color of the cultivated field, but is consistent with the color of the pit berm material.

Corrective Action: Submit a Form 19 documenting the produced water spill. Provide all supporting data and collect a minimum of four samples from the spill sediment deposition area and one non impacted (background) soil sample for pH, EC and SAR laboratory analysis.

Date: 02/19/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402322059	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075897</a>
688000365	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5075887</a>