

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2020

Submitted Date:

03/02/2020

Document Number:

696102421

FIELD INSPECTION FORMLoc ID 309786 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|------------------------------------|-----------------|
| , | | NBL_DJBU_Inspections@nblenergy.com | All Inspections |
| , | | dnr_cogccengineering@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 294467 | WELL | SI | 09/01/2017 | OW | 123-25381 | WELLS RANCH AA 26-08 | TA |

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Reclamation progressing.
 Abandoned Battery SE corner GPS coordinates: 40.460010, -104.399030

Abandoned Centralized Battery formerly served 4 Location IDs (309786, 309784, 413332, 309782).
 (Well(s): 3: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

| Location | | | | |
|--|--|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Adequate | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Invalid Emergency number posted at wellsite. Refer to Rule 210.b. See photo #1. | | | |
| Corrective Action: | Post valid Emergency number at wellsite. Comply w/ Rule 210.b. See photo #1. | | | Date: 04/01/2020 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Iron panel. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Plunger Lift | # 1 | | | corrective date |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | Appears plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 0 | | | |
| Comment: | Battery Abandoned. Equipment removed. | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 0 | | | |
| Comment: | Battery Abandoned. Equipment removed. | | | |
| Corrective Action: | | | | Date: |
| Type: Pig Station | # 0 | | | |
| Comment: | Battery Abandoned. Equipment removed. | | | |

| | | | |
|-------------------------------|---------------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 0 | | |
| Comment: | Battery Abandoned. Equipment removed. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------------------------|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 0 | | | | , | |
| Comment: | Battery Abandoned. Equipment removed. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

| | | | | | | |
|--------------------|---------------------------------------|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 0 | | | | , | |
| Comment: | Battery Abandoned. Equipment removed. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|----------|--|--|
| Type | | |
| Comment: | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Inspected Facilities

Facility ID: 294467 Type: WELL API Number: 123-25381 Status: SI Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 06/2016.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.
 Locked-Out, Tagged Out | LOTO.

Corrective Action: Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On MON 03/02/2020 at approximately 13:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH AA-66N63W /26SENE Location ID: 309786 Well Name: Wells Ranch AA 26-08 API: 05-123-25381 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.460010, -104.399030</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (309786, 309784, 413332, 309782). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>During this inspection the following possible compliance issues were observed: 1.) Invalid Emergency number posted at wellsite. Refer to Rule 210.b. Post valid Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 04/01/2020. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 03/02/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696102422 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082920 |