

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 1: Wellhead Sign



Photo 2: Pumpjack; equipment reconnected



Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 3: Wellhead Sign



Photo 4: Wellhead

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 7: Wellhead Sign



Photo 8: Pumpjack



Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 11: Unused equipment



Photo 12: Unused equipment; all other unused equipment removed.

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 13: Trash



Photo 14: Unused equipment

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 15: Unused equipment



Photo 16: Trash

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 17: Tank Battery Sign



Photo 18: Tank Battery



Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 19: BBLs installed at H2O tank.



Photo 20: Unused risers removed

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 21: Stained soil removed



Photo 22: Stained soil removed

Inspection Photos
Location Name: Walton 25-D Pad
Location ID: 44158



Photo 23: Stained soil removed



Photo 24: Storage of equipment