

Inspection Photos
Operator: BP America
Location #: 067-06911
Date: 2/27/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Vegetation along the edge of fencing is mowed and maintained.



Photo 3. View of dense kochia, up to 5-feet tall, along the northeastern edge of the project area.



Photo 4. View of the reference area, comprised of grass field, in a dormant vegetative condition at this time.