

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hancock Gulch /1 Pad

Location ID: 312419



Photo #0675 from entrance to location



Photo #0676 Multiple places with unused equipment in tank containment.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hancock Gulch /1 Pad

Location ID: 312419



Photo #0677 Multiple places with unused equipment in tank containment.