

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2020

Submitted Date:

03/02/2020

Document Number:

696102435

FIELD INSPECTION FORM

Loc ID 309783 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294463	WELL	PA	04/20/2018	OW	123-25377	WELLS RANCH AA 26-06	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Reclamation progressing.
Abandoned Battery SE corner GPS coordinates: 40.460560, -104.408960

Abandoned Centralized Battery formerly served 4 Location IDs (333283, 309787, 309785, 309783).
(Well(s): 3: Temporarily Abandoned | TA ;2: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 294463 Type: WELL API Number: 123-25377 Status: PA Insp. Status: PA**Workover**

Comment: Plugged & Abandoned | PA.
Well appears to be cut / capped.
Form 6 doc. #401611447 indicates plugging, cut/cap date: 04/20/2018. Approved.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 03/02/2020 at approximately 16:52 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH AA-66N63W /26SENW Location ID: 309783 Well Name: Wells Ranch AA 26-06 API: 05-123-25377 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.460560, -104.408960</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (333283, 309787, 309785, 309783). (Well(s): 3: Temporarily Abandoned TA ; 2: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102436	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083159