

Pit Status Evaluation Form

Pit Overview:

Pit Name: BROOKS 1-1	Facility ID: 114629
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: TRIGG DRILLING CO / 89975	
Updated Operator:	
Form 15 Pit Permit Doc #: 628080	Permit Date: 11/10/1976
Related Facilities: Jordan #34-3 (API 05-009-06037, Facility ID 205626, Loc ID 379002)	

County: BACA			
Township: 32S	Range: 45W	Section: 1	QQ: SENW
Original Latitude/ Longitude: 37.288621 / -102.441507			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 628080 | Date: 11/10/1976 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 565607 | Date: 10/10/1985 |
| Doc #: 200125306 | Date: 1/23/2008 |
| Doc #: 594229 | Date: 9/14/1988 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Related well PA 12/18/1986; passed final inspection 1/23/2008

Pit Status Review Summary:

Based on records review, the pit on location was backfilled prior to the 9/14/1988 PA inspection. Related well was plugged 12/18/1986 and passed final reclamation inspection 1/23/2008. Pit status has been changed to Closed.

