

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #0698 from entrance to location



Photo #0699 Location over grown with debris and weeds.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 312598



Photo #0700 Location over grown with debris and weeds.



Photo #0702 Location over grown with debris and weeds.