

27A pad  
API: 05-103-11020  
Inspection: 700400315



39 8518, -108 37266, 6360 9ft, 263°  
03/03/2020 12:08:49 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 1. Location.



27A pad  
API: 05-103-11020  
Inspection: 700400315



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 2. Well head.



27A pad  
API: 05-103-11020  
Inspection: 700400315



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Chemical & separators.**



27A pad  
API: 05-103-11020  
Inspection: 700400315



39.8515, -108.37346, 6368.0ft, 301°


03/03/2020 12:11:14 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**

27A pad  
API: 05-103-11020  
Inspection: 700400315



39.85176, -108.37361, 6359.7ft, 2°  
03/03/2020 12:12:29 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tank liner holes.**