

Final Reclamation Inspection

March 3, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 335731

Inspection Document #: 697501183

Adams County, CO

NENW Section 13 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NORTH COLORADO #6
Location ID: 335731



Photo 1. Photo taken from the northern well and tank battery location, facing East. Photo illustrates Operator appears to have initiated final reclamation activities.

Inspection Photos
Location Name: NORTH COLORADO #6
Location ID: 335731



Photo 2. Photo taken from the northern well and tank battery location, facing South. Photo illustrates equipment remains at location.

Inspection Photos
Location Name: NORTH COLORADO #6
Location ID: 335731



Photo 3. Close up photo taken from the western well and tank battery location, facing West. Photo illustrates equipment remains at location.