

Inspection Photos

Loc#335052

Operator: Ursa

Inspection #: 692401907

Inspection Date: 2/21/20





Photo#1:
Overview of Location from entry.

February 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa CSF T Loc#335052



Photo#2:
Wildlife Escape Board are improperly adjusted.

February 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa CSF T Loc#335052