

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2020

Submitted Date:

03/04/2020

Document Number:

696102466

**FIELD INSPECTION FORM**Loc ID 302575 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299564	WELL	PR	10/25/2019	OG	123-29416	WELLS RANCH USX AA 25-03	TA

**General Comment:**

This is a WELL / ABANDONED BATTERY inspection.  
 Well(s): 1: Temporarily Abandoned | TA.  
 Battery: Abandoned. ALL equipment has been removed.  
 Reclamation progressing.  
 Abandoned Battery SE corner GPS coordinates: 40.460370, -104.389954

Abandoned Centralized Battery formerly served 4 Location IDs (302575, 310016, 302576, 310009).  
 (Well(s): 3: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: <a href="#">Battery Abandoned. Equipment removed.</a>						
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: <a href="#">Battery Abandoned. Equipment removed.</a>						
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 299564 Type: WELL API Number: 123-29416 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

**Comment:** Temporarily Abandoned | TA.  
 Battery Abandoned: All Equipment Removed.  
 COGCC records indicate last production: 04/2015.  
 SI/TA well per variance doc. #401474555. (NOBLE).  
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.  
 Locked-Out, Tagged-Out | LOTO.

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 03/04/2020 at approximately 15:05 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: WELLS RANCH USX AA-66N63W /25NENW            Location ID: 302575            Well Name: Wells Ranch USX AA 25-03            API: 05-123-29416            Location County: Weld County, Colorado            Weather: Mostly sunny, dry.</p> <p>While there, I observed:            Well(s): 1: Temporarily Abandoned   TA.            Battery: Abandoned. ALL equipment has been removed.            Reclamation progressing.            Abandoned Battery SE corner GPS coordinates: 40.460370, -104.389954</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (302575, 310016, 302576, 310009).            (Well(s): 3: Temporarily Abandoned   TA ; 1: Plugged &amp; Abandoned   PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/04/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102467	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085950">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085950</a>