

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #1 Separators & ECD's



Photo #2 Meter Runs & Tank Battery

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Colorado Oil and Gas Conservation Commission
40.34861, -104.45175, 4511.4ft, 177°
03/05/2020 07:09:06 AM



Colorado Oil and Gas Conservation Commission
40.34777, -104.4511, 4506.5ft, 139°
03/05/2020 07:20:20 AM

Photo #3 Tank Battery

Photo #4 Frac Tank for Sand cans

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #5 Glycol



Photo #6 Compressors

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #7 Wells

Photo #8 Wells & Sand Cans

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #9 Stained Soil

Photo #10 Stained Soil

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774




Photo #11 Stained Soil

Photo #12 Stained Soil

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Colorado Oil and Gas Conservation Commission
40.34831, -104.45183, 4519.9ft, 27°
03/05/2020 07:11:23 AM



Colorado Oil and Gas Conservation Commission
40.34831, -104.4518, 4523.7ft, 37°
03/05/2020 07:11:30 AM

Photo #13 Stained Soil

Photo #14 Trash & Unused Equipment

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774




Photo #15 Unused Equipment

Photo #16 Unused Equipment

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #17 Trash



Photo #18 Unused Equipment

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #19 Stained Soil

Photo #20 Stained Soil

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #21 Unused Equipment

Photo #22 Trash

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #23 Trash

Photo #24 Unused Equipment

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #25 Trash

Photo #26 Trash

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Colorado Oil and Gas Conservation Commission
40.34836, -104.45068, 4513.7ft, 235°
03/05/2020 07:24:51 AM



Colorado Oil and Gas Conservation Commission
40.34844, -104.45068, 4512.7ft, 260°
03/05/2020 07:25:09 AM

Photo #27 Trash

Photo #28 Trash

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #29 Stained Soil

Photo #30 Unused Equipment

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Photo #31 Trash

Photo #32 Trash

Inspection Photos
Location Name: Wetco Farms A-4 Pad
Location ID: 431774



Colorado Oil and Gas Conservation Commission
40.34349, -104.45157, 4507.9ft, 132°
03/05/2020 07:51:01 AM

Photo #33 Trash



Colorado Oil and Gas Conservation Commission
40.34794, -104.45086, 4502.9ft, 113°
03/05/2020 07:52:26 AM

Photo #34 Blowdowns