

KP Kauffman Company INC, Kiowa Creek 21-9 1
039-06544

Inspection #688307144

3/4/2020

Routine Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission

39.54607, -104.45243, 5823.5ft, 242°

03/04/2020 08:47:37 AM




Colorado Oil and Gas Conservation Commission
39.54611, -104.45246, 5826.8ft, 201°
03/04/2020 08:47:53 AM



Colorado Oil and Gas Conservation Commission

39.5461, -104.45255, 5820.2ft, 151°

03/04/2020 08:48:09 AM



Colorado Oil and Gas Conservation Commission
39.54606, -104.45259, 5820.2ft, 134°
03/04/2020 08:48:22 AM

A photograph of a wellhead in an arid, desert-like environment. The wellhead is covered by a circular, weathered metal plate. A white label is attached to the wellhead, featuring the text "PRODUCED WATER" in bold, black, sans-serif capital letters. Below this, the number "25" is visible, followed by a partially obscured word that appears to be "DE". The surrounding ground is dry, sandy, and covered with sparse, dry vegetation. Long shadows are cast across the scene, indicating it is either early morning or late afternoon.

PRODUCED WATER
25 DE

Colorado Oil and Gas Conservation Commission

39.54595, -104.45248, 5826.8ft, 274°

03/04/2020 08:50:46 AM



Colorado Oil and Gas Conservation Commission

39.54597, -104.45247, 5833.3ft, 238°

03/04/2020 08:50:50 AM



Colorado Oil and Gas Conservation Commission
39.54609, -104.45258, 5820.2ft, 291°
03/04/2020 08:48:15 AM



Colorado Oil and Gas Conservation Commission
39.54653, -104.45261, 5836.6ft, 18°
03/04/2020 08:49:17 AM



Colorado Oil and Gas Conservation Commission
39.54657, -104.45259, 5833.3ft, 2°
03/04/2020 08:49:33 AM