

Inspection Photos
Operator: BP America
API#: 067-06816
Date: 3/2/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope facing eastward, revegetation is largely comprised of intermediate wheatgrass. Intermediate wheatgrass is a non-native grass species that is not representative of reference area vegetation.



Photos 3/4. View of dense musk thistle rosettes within the western project area.



Photo 5. View of reference area vegetation comprised pinyon juniper woodland with herbaceous understory comprised of grasses such as Indian ricegrass and muttongrass and forbs in a dormant vegetative condition.