

## Pit Status Evaluation Form

## Pit Overview:

<b>Pit Name:</b> ZIEGLER	<b>Facility ID:</b> 115424
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b>	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b> 704677	<b>Permit Date:</b> 2/19/1981
<b>Related Facilities:</b> ZIEGLER #1 (API 05-063-06071 - Facility ID 213512 - Loc ID 385021)	

<b>County:</b> Kit Carson			
<b>Township:</b> 8s	<b>Range:</b> 45W	<b>Section:</b> 3	<b>QQ:</b> SWSW
<b>Original Latitude/ Longitude:</b>		/	
<b>Updated Latitude/ Longitude:</b> 39.374098		/ -102.42596	
<b>Basis for Location Change:</b>			
Created lat/long at well location			

**Pit Inspection/Information Request:**

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                 |
|-------------------------------------|---|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 704677          | Date: 2/19/1981 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 704691         | Date: 4/10/1985 |
|                                     | Doc #: 434221                               | Date: 7/13/1988 |
|                                     | Doc #:                                      | Date:           |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:           |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:           |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:           |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:           |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                 |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                 |
| <input type="checkbox"/>            | Other:                                      |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

Associated well was plugged 7/16/1987

#### Pit Status Review Summary:

Inspection reports document a 15'x50' pit on location. Associated well was plugged 7/16/1987 and pit was backfilled prior to 7/13/1988 PA inspection. Pit Status has been changed to closed.

