

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> CHAMPLIN KIRSCHMER 1	<b>Facility ID:</b> 115419
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> CITATION OIL & GAS CORP / 17180	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> CHAMPLIN KIRSCHMER #1 (API 05-063-06049 - Facility ID 213490 - Loc ID 324932)	

<b>County:</b> Kit Carson			
<b>Township:</b> 11S	<b>Range:</b> 44W	<b>Section:</b> 21	<b>QQ:</b> SWSW
<b>Original Latitude/ Longitude:</b> 39.075653 / -102.351656			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                 |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:           |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 704709         | Date: 8/20/1985 |
|                                     | Doc #: 489548                               | Date: 9/7/1995  |
|                                     | Doc #: 200130438                            | Date: 4/15/2008 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:           |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:           |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:           |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223463              | Date: 2/27/1998 |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                 |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                 |
| <input type="checkbox"/>            | Other:                                      |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location

#### Pit Status Review Summary:

Based on records review, any pits on location were backfilled prior to 8/20/1985 field inspection; inspection reports document a steel produced water tank on location. Pit status has been changed to closed.

