

Interim and Stormwater Inspection

January 25, 2020

Operator: PDC Energy (69175)

Location ID: 244306

Inspection Document #: 701100050

Weld County, CO

NWSW 17 5N64W

Stephen Lunt
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Dunn/ Miller #1
Location ID: 244306



Photo 1. Photo taken from GPS coordinate for former wellsite looking North. No current oil and gas activities observed on site.



Photo 2. Photo taken from GPS coordinate for former wellsite looking East.. No current oil and gas activities observed on site.

Inspection Photos
Location Name: Dunn/ Miller #1
Location ID: 244306



Photo 3. Photo taken from GPS coordinate for former wellsite looking South. No current oil and gas activities observed on site. .