

Inspection Photos

Location Name: NPR O04-696 Pad

Location ID: #414231

Inspection Date: February 28, 2020



Photo #1 – View of covered cellars in center of pad, looking east.



Photo #2 – Cuttings management area located on east end of pad. See doc #402308676 for Drill Cuttings Waste Management Plan.



Inspection Photos
Location Name: NPR O04-696 Pad
Location ID: #414231
Inspection Date: February 28, 2020



Photo #3 – Capped 4" flowline riser on west end of pad.



Photo #4 – Flowline on west end of pad was tagged out on inspection date.

