

# Final Reclamation Inspection

February 25, 2020

Operator: HIGHPOINT ENERGY LLC - 10544

Location ID: 418750

Inspection Document #: 697501188

Weld County, CO

SESW Section 15 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the well and tank battery location, facing Northwest. Photo illustrates Operator has removed all the major equipment but has not conducted surface reclamation (i.e., remove gravel, contour, ect...).



**Photo 2.** Photo taken from the well and tank battery location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: RBF /15B  
Location ID: 418750



**Photo 3.** Photo taken from the well and tank battery location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: RBF /15B  
Location ID: 418750



**Photo 4.** Photo taken from the well and tank battery location, facing South. See comments under Photo 1.





**Photo 5.** Photo taken from the western well and tank battery location, facing West.  
Photo illustrates the access road.



**Photo 6.** Photo taken from the northeastern location, facing North. Photo illustrates unused equipment left at location.





**Photo 7.** Photo taken from the northeastern area, facing East. Photo illustrates oil and gas equipment associated with the location remains.