

RGU 24-29-198
API: 05-103-10611
Inspection: 700400335



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

RGU 24-29-198
API: 05-103-10611
Inspection: 700400335



39.92878, -108.41766, 6320.7ft, 306°
03/05/2020 11:39:58 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

RGU 24-29-198
API: 05-103-10611
Inspection: 700400335



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

RGU 24-29-198
API: 05-103-10611
Inspection: 700400335



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank battery.

RGU 24-29-198
API: 05-103-10611
Inspection: 700400335



39.93039, -108.4187, 6304.6ft, 156°
03/05/2020 11:37:14 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Location signs.