

Inspection Photos

Location Name: LARAMIE ENERGY LLC Domestic Tap /9-5 Pad

Location ID: 455946



Photo #0709 Domestic tap.



Photo #0711 In line fisher regulators.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Domestic Tap /9-5 Pad

Location ID: 455946



Photo #0710 Pressure plate of primary regulator.





Photo #0712 Pressure plate of secondary regulator.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Domestic Tap /9-5 Pad

Location ID: 455946



Network:Mar 5, 2020 at 2:45:04 PM MS
Local:Mar 5, 2020 at 2:45:04 PM MS
+39.2081,-107.894



Network:Mar 5, 2020 at 2:44:40 PM MS
Local:Mar 5, 2020 at 2:44:40 PM MS
+39.2081,-107.894

Photo #0715 Up stream fittings.

Photo #0714 Down stream fittings.