

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W /23NESE

Location #: 302619



Photo #1

Wells Ranch USX AA 23-09 (05-123-29488) Wellsite
Temporarily Abandoned | TA



Photo #2

Wells Ranch USX AA 23-09, 23-10 Battery site
Abandoned: All Equipment Removed
Reclamation progressing
Formerly served Wells Ranch USX AA 23-15, 23-16
(Plugged & Abandoned | PA)