

Inspection Photos

Location Name: WELLS RANCH USX AA-66N63W /23SESE

Location #: 310043



Photo #1

Wells Ranch USX AA 23-16 (05-123-25802) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing



Photo #2

Wells Ranch USX AA 23-09, 23-10 Battery site

Abandoned: All Equipment Removed

Reclamation progressing

Formerly served Wells Ranch USX AA 23-15, 23-16

(Plugged & Abandoned | PA)