

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/06/2020

Document Number:

696102488**FIELD INSPECTION FORM**Loc ID 310043 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nbl energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295786	WELL	PA	06/07/2016	OW	123-25802	WELLS RANCH USX AA 23 -16	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.468904, -104.398991

Abandoned Centralized Battery formerly served 4 Location IDs (302619, 310042, 302620, 310043).

(Well(s): 2: Temporarily Abandoned | TA ; 2: Plugged & Abandoned | PA).

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 295786 Type: WELL API Number: 123-25802 Status: PA Insp. Status: PA

Workover

Comment: Plugged & Abandoned | PA.
Well appears to be cut / capped.
Form 6 doc. #401068000 indicates plugging, cut/cap date: 06/07/2016. Approved.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 03/05/2020 at approximately 15:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX AA-66N63W /23SESE Location ID: 310043 Well Name: Wells Ranch USX AA 23-16 API: 05-123-25802 Location County: Weld County, Colorado Weather: Mostly sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.468904, -104.398991</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (302619, 310042, 302620, 310043). (Well(s): 2: Temporarily Abandoned TA ; 2: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102489	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087358