

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/06/2020

Document Number:

696102490**FIELD INSPECTION FORM**Loc ID 420996 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nbl energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421155	WELL	PA	06/10/2016	OW	123-32830	WELLS RANCH AA 24-03X	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.475707, -104.389963

Inspected FacilitiesFacility ID: 421155 Type: WELL API Number: 123-32830 Status: PA Insp. Status: PA**Workover**

Comment: Plugged & Abandoned | PA.
Well appears to be cut / capped.
Form 6 doc. #401073066 indicates plugging, cut/cap date: 06/10/2016. Approved.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 03/05/2020 at approximately 16:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH AA /24-03 Location ID: 420996 Well Name: Wells Ranch AA 24-03X API: 05-123-32830 Location County: Weld County, Colorado Weather: Mostly sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.475707, -104.389963</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102491	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5087359