

## Pit Status Evaluation Form

## Pit Overview:

<b>Pit Name:</b> UPRR 43 PAN AM "O"	<b>Facility ID:</b> 117962
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> AMOCO PRODUCTION COMPANY / 2500	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b> 696852	<b>Permit Date:</b> 11/28/1979
<b>Related Facilities:</b> UPRR 43 PAN AM O #1 (API 05-123-09668 - Facility ID 241877 - Loc ID 318673)	

**County:** WELD  
**Township:** 1N      **Range:** 68W      **Section:** 13      **QQ:** CNE  
**Original Latitude/ Longitude:** 40.054868 / -104.947204  
**Updated Latitude/ Longitude:** /  
**Basis for Location Change:**

**Pit Inspection/Information Request:**

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |   |                  |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 696852          | Date: 11/28/1979 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 41961          | Date: 11/14/1995 |
| Doc #: 500164626  | Date: 7/22/1999  |
| Doc #:  | Date:            |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #:              | Date:            |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #:                          | Date:            |
| <input type="checkbox"/> COGIS Document – Doc #:                                | Date:            |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986              | Date: 8/25/1997  |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #:                 |                  |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/> Other:   |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

Pit was replaced with a fiberglass produced water tank prior to 8/25/1997 pit inventory report

#### Pit Status Review Summary:

Inspections document an unlined pit on location, which was replaced by a fiberglass produced water tank prior to the 1997 pit inventory report. Pit status has been changed to closed.

