

Pit Status Evaluation Form

Pit Overview:

Pit Name: GETZ UNIT	Facility ID: 118709
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: HELMER GETZ UNIT TRUE #1 (API 05-123-09668 - Facility ID 241877 - Loc ID 318673)	

County: WELD			
Township: 1N	Range: 66W	Section: 18	QQ: CNW
Original Latitude/ Longitude: 40.054668 / -104.82507			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|-----------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 30092 | Date: 1/2/1996 |
| Doc #: 200092777 | Date: 4/24/2006 |
| Doc #: | Date: |
| <input checked="" type="checkbox"/> Form 27 Remediation Workplan – Project #: 4450 | Date: 2/23/2009 |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986 | Date: 8/25/1997 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Pit was replaced with a fiberglass produced water tank prior to 8/25/1997 pit inventory report

Pit Status Review Summary:

Inspections document an unlined pit on location, which was replaced by a fiberglass produced water tank prior to the 1997 pit inventory report. An environmental assessment was performed at the Helmer Getz Unit True Tank Battery under remediation project #4450, which was closed 6/19/2009. Pit status has been changed to closed.

