

Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



Photo #0718 from entrance to location



Photo #0720 Debris around equipment.

Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



Photo #0721 Debris around equipment.



Photo #0719 Unused piping by meter run.