

RGU 34-19-198  
API: 05-103-10598  
Inspection: 700400343



39.94445, -108.43178, 6480.7ft, 112°  
03/05/2020 12:32:11 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

RGU 34-19-198  
API: 05-103-10598  
Inspection: 700400343



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 2. Separator.



RGU 34-19-198  
API: 05-103-10598  
Inspection: 700400343



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 3. Tank battery.



RGU 34-19-198  
API: 05-103-10598  
Inspection: 700400343



39 94444, -108.4316, 6468 1ft, 201°  
03/05/2020 12:32:37 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Deadman.**